

Ship Otago  
Lat 44° N Long 16° W.  
1 Oct. 1869.

J. Williamson Esq.  
Lloyd's Surveyor  
Greenock

Dear Sir

As you requested I  
send a few lines anent the  
Otago's rudder.  
I am glad to be able to inform  
you that it is effectually  
cured. We have encountered  
all kinds of weather since  
leaving Greenock and had severe  
gales both favourable and  
contrary, accompanied by  
very heavy seas, and during  
it all the rudder has not given  
a shake. In fact it is now as  
steady or even steadier than  
I ever saw a rudder.

I am Sir

Yours truly

Wm. Stewart.

GRk295-0253(112)

O.T.G.



Stern-post, siding and moulding .....  
After deadwood plate, breadth and thickness...  
Distance of Frames from moulding edge to

15 x 16 1/2  
15 1/2 x 14 1/8  
21.

P.S. Please show this to Mr.  
Duncan as there is a ship  
close to I have no time to  
write him  
C.R.W.



© 2020

Lloyd's Register  
Foundation

GRH29S-0253(212)