

2nd. On the plating during the process of riveting
3rd. When the beams were in and fastened,
and before the decks were laid

Nov 6. 22. 29; Dec. 4. 5. 12. 14. 20. 27.
1883 Jan. 13. 16. 18. 22. 26; Feb. 3. 6. 7. 15. 1

REPORT, No. 424 FROM
ON THE J. S. North

Greenock

DATE 28/5/83

REMARKS OF THE CHIEF SURVEYOR.

It is submitted that the vessel appears
eligible to be classed 100R.1 as
recommended

10k

Steel Beams

GRK300-0112



© 2019

Lloyd's Register
Foundation