

No. 1153.

(Received in London Office,

TESTS OF BOILER STEEL.

Tests of 1 Steel plate manufactured by the *Earl Co. & Co. Scotland Brechin*
for Boiler No. 77 to be constructed by *Messrs. J. & W. Ferguson & Co. of Glasgow*
for *S.S. No. 77 building by Messrs. Murdoch & Murray*
Date first visit *18th Aug. 83* last visit *16th Aug. 83* No. of Visits *1*

The *plate* specified in the ~~accompanying~~ copy of Advice Notes were rolled from *one* charge. The tensile test has been applied to *one* sample as set forth below, and the temper and bending tests *proved satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
<i>1</i>	<i>16.0 x 8.1/8 Rad. 2366 9 1/2 x 9 1/8</i>	<i>1</i>	<i>8987</i>	<i>1</i>	<i>.62</i>	<i>1.15</i>	<i>.713</i>	<i>21.4</i>	<i>30.0</i>	<i>22.0</i>	

Fee £ : :
Expenses £ : :
£ : :

To be paid by *the manufacturer* *Glasgow*
25/8/83

GRK 302-0200

THE LLOYD'S REGISTER OF COMPANIES

THE LLOYD'S REGISTER OF COMPANIES

William & Douglas
Hick
Hick



© 2019

Lloyd's Register
Foundation