

S. S. "Vandal"

4

Chain Cables for the Steel Screw Steamer No. 35 now
building by the Campbeltown S.B. Co with a view to class 100A1.

The weight of the chain cables supplied to this vessel is
269.3.19, instead of 274.1.0 as required by Table 22 of the Rules,
under which the vessel was built.

The Manufacturer of the chain cables has been communicated
with respecting this deficiency in the weight of the cables, and
states that the requirements of amended Table 22 were never
communicated to him, and the principal cause of this deficiency in
the weight is owing to the studs being somewhat small, but he will
be careful it shall not occur again.

Under these circumstances, the case is submitted to the
favourable consideration of the Committee.

V. S. M.

16/11/92.

Ans: 12 476. 11. 92

Ans. 17th

2 test certificates.

Approved by S.C.

17. 11. 92

ajd



© 2020

Lloyd's Register
Foundation

GR4323-0244