

Assigned

The Surveyors are requested not to write on or below the space for Committee's Minutes.

Committee's Minute

TUES. 27 AUG 1895

The amount of Entry Fee..	£	:	:	When applied for,	18
Special	£	:	:	When received,	18
Donkey Boiler Fee	£	:	:		
Travelling Expenses (if any)	£	:	:		

Certificate (if required) to be sent to

A. L. Brown
Engineer Surveyor to Lloyd's Register of British & Foreign
Greenock District

General Remarks (State quality of workmanship, opinions as to class, &c.)

David C. Smith
The foregoing is a correct description,
Manufacturer.

SPARE GEAR. State the articles supplied:—

Working pressure		tested by hydraulic pressure to		Pressure to which they are adjusted		If fitted with easing gear		Description of safety valves		Where fixed	
No. of safety valves		Area of each		Diameter of donkey boiler		Length		Material of shell plates		Thickness	
enter the donkey boiler		Description of riveting long seams		Diameter of rivet holes		Whether punched or drilled		Pitch of rivets		Thickness	
Lap of plating		Per centage of strength of joint		Rivets		Thickness of shell crown plates		Radius of do.		No. of Stays to do.	
Dia. of stays.		Diameter of furnace Top		Bottom		Length of furnace		Thickness of furnace plates		Description	
joint		Thickness of furnace crown plates		Stayed by		Working pressure of shell by rules		Thickness of water tubes			
Working pressure of furnace by rules		Diameter of uptake		Thickness of uptake plates							