

Are they fixed sufficiently high on the ship's side to be seen without lifting the stowenout plates yes

It is submitted that the Cardiff Surveyors
be requested to forward the particulars of
the fitting of the drain cock to the main
steam pipe as early as possible.

Dr. to Cof 14/10

GRK 332-6673

Lloyd's Register
Foundation
14. 10. 95.

with easing gear yes

Length 11' 0"

Material of shell plates Steel

Thickness 1 7/16"

Description of riveting: circum. seams