

S. S. Craigrowan

Gls 15865.

It is submitted that before dealing with this case the Surveyors attention should be called to the heating

Lloyd's Register of British  
and Foreign Shipping.  
342, Argyle Street, Glasgow.

ference

TELEPHONE No 4586.

LOYDS REGISTER  
LONDON.

CR. 10 MAR. 1898

182

9<sup>th</sup> March 1898

Sir

In reply to your further Communication regarding the heating surface in the boilers of the S. S. "Craigrowan" Glasgow Report No 15865 I beg to state that in the first instance the Heating surface of Tubes only had been taken of one boiler and by doubling this, led to the error the second time. The matter has now been put right as far as the fees are concerned and I will beg of you will get the correction made on the Report Heating Surface 3888 ft and 250 H. and Copy from amended account.

Regretting the trouble occasioned by these errors.

Secretary  
Lloyd's Register  
London

Yours Obedient Servant  
James Mollison

GRK340-0090



as

10 MAR 1898

Alfred Mr. Loring  
+ Mr. Whitely

W. A. note

as.  
10.398.



© 2019

Lloyd's Register  
Foundation