

J. L. Crayson

Gls 15865.

It is submitted that before dealing with this case the surveyors attention should be called to the heating surface as given on the drawing <sup>which is 3888</sup> & on their report <sup>which is 1598</sup> & they should be requested to alter this & the H. H. P. in accordance with it. they should also be requested to forward a drawing of the donkey boiler as from the dimensions given on the report the furnace does not appear to be eligible for the working pressure of 20 lbs.

Report to Gls  
4/3/98

Gls  
3.3.98

Gls  
3/3/98

© 2019

Lloyd's Register  
Foundation

GRK340-0091