

Received by Chief Surveyor

Received from Chief Surveyor

VESSEL'S NAME

Steel S.S. "Febrero"

Report

Lyk

No. *12095*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

DAMAGE.

Damage through *collision with a dock wall*
Vessel examined in dry dock

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

(of wrought iron)
The stern frame removed, partly renewed & the frame refitted.
The rudder renewed. Two new brackets fitted to stern cant frames
& minor repairs.

It is submitted the vessel is worthy to remain classed *100 A.1 "pt. awng.*
dk. with fbd" with record of Survey *6, 98 P. Lyl.* as recommended.

100 A.1

"pt. awng. dk. with fbd"
6, 98 P. Lyl.



© 2019

J. H. T.
2/7/98

LRH322-0014