

COPY.

S.

17th January, 1900.

Gentlemen,

I am in receipt of Mr. Phillips's letter of the 16th instant, respecting the case of the steel steamer "GRESHAM", your First Entry Report No. 12582, and with reference thereto, I have to point out that the survey fees are not yet paid on the hull of this vessel, and that no intimation of the kind desired can therefore be given to the Owner.

If the fees are previously paid the report will be submitted to the Classing Committee at their meeting on Friday next.

I am, Gentlemen,

Your obedient Servant,

pro Secretary.

The Surveyors,

GREENOCK.



© 2020

Lloyd's Register
Foundation

GRK350-0045

Bridge or Pt. Awng. Deck, Angle,
Bulb Angle Plate, or Tee Bulb....
Angles on Upper Edge

5	3	4	5	3	4
---	---	---	---	---	---

Angles on ditto, No.
Poop Deck Stringer Plate, breadth & thickness