

F.E.

Received by Chief Surveyor 16. 3. 00

Received from Chief Surveyor

SEL'S NAME Sa. S.S. "Sirius" Report Sur No. 12621

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	7/20"	Proportion
Description of Framing:— <u>deep framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A1 ("Steel") "Spar Deck" as recommended.

∇ 100 A1 ("Steel") "Spar Deck"

1 DR (St) & Spar DR (St) & deep framing.

N.B = Cee DB a 102' a E & B 40' f 140' 877E APT 63E

FK 5BH Cee A & CP P20' B72' F33'

C.H.f.
16/3/00

It should be pointed out to the Surveyor that the equipment number as stated in the report (33385) appears to be in error, as the number as corrected on the approved photo print of midships section is 33885, and the number in the report of the section titled "Quarterns" is 33856, but he should state if this is so. C.H.f.

GRK350-0159

Quarter, 'tween Dks., " "	2 3/4	96 2 3/4	96	Forecasting Deck Stringer Plate, 1/2" thick & 12" high	30
in Hold " "	4	96 4	96	" Angle on ditto	37 3 1/2
				Tie Plates	14