

Urgent, wire required.

Russell & Co's. Nos.463 & 468.

Equipment No. of 463 is 33912.

do. do. 468 do 37824.

The Builders wire stating they have just discovered that two of the anchors belonging to No.468 have been placed on board No.463 in mistake, making the collective weight of the anchors of No.463 $\frac{1}{2}$ Cwt. less than required by the Rules.

As the vessel sails from Glasgow loaded at 4 o'clock to-morrow morning, and the Owners have agreed to accept the anchors now on board, the Builders hope, under the circumstances, that the Committee will approve of the same, and they wish to be informed of the Committee's decision by wire.

It is submitted under the circumstances the anchors now on board No.463 might be approved for the figure 1 and the Builders should be informed by wire accordingly.

Michael J. G.

*Let. to Bldrs
Spec. to G.R. 27/11/00.*

L.B.

J.P.L.

C.H.P.
© 2020

Lloyd's Register
Foundation

GRK 354-0080