

Port of Greenock

Oct 26<sup>th</sup> 1904

REPORT ON MASTS, SPARS, AND RIGGING.

Gentlemen:

Having, in accordance with your instructions, examined  
Masts, Spars, and Rigging, and Iron Work of same, of the  
S. itonia

we to report that I found The above in good  
Sound Condition with the exception  
of Cargo Derrick aft that is  
badly Sprung & Broken;

Please Note) The Rigging on Fore Mast  
may not be fit to go Back in the  
the riggers Cut it.

J Gallacher

Foreman Shipwright

£ 1 : 0 : 0

Surveyors,

Lloyd's Register of British & Foreign Shipping,



© 2019

Lloyd's Register  
Foundation

GRK355-0083

unsuccessful to drill the bottom. Chain cable raised