

27/8/95.

Received from Chief Surveyor.....

Report *W Hpl.* No. *9763*

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

### Nature of Survey

+100 A. 1. (Pl.) With Freeboard.  
1 Dk. (Iron), 2 Tiers of Beams, & Deep Framing.  
W.B. = Cell. D.B. a 100', nE. 22', / 120', 604 t.  
F.K. Cem.

C. H. J. J. B.  
27/8/96

© 2019

Lloyd's Register

HL 375-0155

**W. T. BULKHEADS**  
**PARTITION „**  
**LONGITUDINAL „**

No. of Side Stringers

Size of Angles or Tee Bars to Web-Frames