

Is the riveted work proper?  
Are the liners between the frames and plates solid single pieces?

Do the holes for riveting plate to frames, butt

(Form No. 81.)

# FREEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office

Port *Port Harlepool*

Vessel's Name *"Rao Blba"* Official No.

No. in Reg. Book

Iron or Steel *Steel* State whether Classed by Lloyd's Register *1100M Steel*

Name of Owners *"Rao" of C. L.* Date of Verification *25/9/95.*

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	ft.	ins.
From centre of disc to top of statutory deck line	9	0
at <del>awning or</del> part-awning deck	5	ins.
Fresh water line above centre of disc	4 1/2	ins.
Indian Summer line above centre of disc	4 1/2	ins.
Winter line below centre of disc	9	ins.
Winter North Atlantic line below centre of disc		ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk.	ins.
	at <del>awning or</del> pt.-awning dk.	1 1/2 ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(To be filled up in London Office.)

Statement No. Date of Committee's Minute

Moulded Depth for record 23 ft. 10 ins.

Freeboards compared and found correct by date

Is fee paid?

Form for Certificate

Instructions

date

Certificate written

Noted for posting

55.—L.R.P.H.—2,000.—Transfer Ink.—3/8/95.

Certificate\* £

received by me,

22.11.1895

© 2020

Lloyd's Register Foundation

HPL376-0135