

F.E.

by Chief Surveyor 6.1.98

Received from Chief Surveyor _____

VESSEL'S NAME St. S. S. "Victoria" Report Apr. No. 10433

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	✓	✓
Description of Framing:— <u>Bulb Angle as approved.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A1 ("Steel") as recommended.


 ∇ 100 A1 ("Steel")

3 DR. (Stt) & web frames

M.B. = Cell DB a 130' w E & B 80' f 143' 1082 t DTA 50' 989 t APT 22 t.

FK & BK 3" 8 BH. Asp. A & CP.


+ L. h. C. 1. 98.


6.1.98.

P 86' B 230' Shelter dk f 20' F 98'



© 2019


 Lloyd's Register
 Foundation

HPL 380-0284

The Surveys should be requested to state that the vessel is