

1.

Sent to Chief Surveyor 15. 3. 00

Received from Chief Surveyor

VESSEL'S NAME *S.S. S. S. Rapidan*

Report *Hpl.* No. 10581

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

When due

It is submitted that the record of corrections in the Register Book - *P 84' B 245' F 103'* be deleted, and the record *^{on Shutter dk} B 122'* be inserted.

C. H. J.
15/3/00

made C. H. J. 20/3/00.

notes P. C. J. 20/3/00

note. as in the case of the s.s. "Manchester Shipper", No 35 in PR supp.



© 2019

Lloyd's Register Foundation

HPL 381-0237

HPL 381-0238

Handship Section