

Chief Surveyor 10099 Received from Chief Surveyor _____
VESSEL'S NAME USS Landa Report Apr No. 10888

For the CHIEF SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____ When due _____

It is submitted that the record of water ballast in the Register Book be amended as below:

Amend WB = MT 28' FT 19' a T 18'
to

WB = MT 28' FPT 53t APT 35t

J. H. T.
12/6/99.



© 2019
Lloyd's Register
Foundation

Mr. White
+ Mr. Asrough.

HPL385-0081

WRITTEN.

HPL385-0083

Re
s c

been removed
record of fresh
exchange from