

14th November, 1899.

Sir,

I have to acquaint you that I am in receipt of a report from the Society's Surveyors at West Hartlepool on the steamer "Elan" from which it appears that two hand pumps require to be tested, a bronze anchor supplied & compared with the certificate of test and the donkey boiler safety valves adjusted under steam.

The Owners state that this will probably be done on the vessel's arrival at your port, and I shall, therefore, be glad if you will give the case attention. I may add that a record of 11,423-10.99 & 11,426-10.99 has been assigned subject to this being done.

I am, Sir,



© 2019

Lloyd's Register  
Foundation