

Received by Chief Ship Surveyor 15. 10-15

Received from Chief Ship Surveyor

VESSEL'S NAME Iron S. S. "Agnes" Rpt. Hpl No. 15162

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

Damage through striking dock wall

(see Brg rpt 14859
" " " 14682)

now repaired as follows:-

| | Plates | Frames | R. Frames | Floors | Beams | Str. Plates | Dk. Plates |
|--|---------------------------------|--------|-----------|-------------------------|-------|--------------------------|------------|
| Renewed | 3 | 3 pt | | | | 1 pt. | |
| Removed and faired or repaired..... | 1 | | | | 1 | | |
| Faired or repaired in place..... | | 1 | | | | | |
| Other items:- | Vessel examined afloat renewed. | | | Minor repairs effected. | | One Louse pipe effected. | |

Repairs (wear + tear)

Peating under donkey boiler renewed.
Minor repairs effected.

It is submitted the vessel is worthy to remain as classed with out record of Survey as recommended without special condition.

As now - without.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



HPL390-0349

Gothe
ation (which
ster Book &
Year
Assigned
expired
med) as
verified
ENS NOT
is purpose
No. H
to
ice
Sheer
Shee
u De
deck a
One Han
M. of Wood
on Felt.)
on, Month
, &c.
ascertained
edges rem
atter
of 33
if now ra
board)
ngth
arps
unning Rigg
ister Book
ssed and to
ligi