

held while built
as per Section

2nd. On the plating during the process of riveting

3rd. When the beams were in and fastened.

17 Nov 10 Sec 28


1883 41 211-111-111-111

REPORT, No. 5282 FROM Hull DATE 16/4/83
ON THE Alice

REMARKS OF THE CHIEF SURVEYOR.

It is submitted that this vessel merits the
favorable consideration of the Committee to
be classed 90A1 as recommended
10k (ton)

©2021



Lloyd's Register
Foundation

HUL395-0199