

REPORT of SURVEY for REPAIRS, &c.

Survey held at Hull Date, first Survey May 9th Last Survey June 15th 1883.

on the S.S. "Saint Mark" Master Johnson.

Under Tonnage Deck 1559 Built at Stockton When built 1878 10th  
Spar Deck, or Awaiting Deck  
Poop  
Raised Qr. Dk.  
Houses on Deck  
Forecastle 1408  
Tonnage, as per Rule  
Tonnage, cut on Beam  
Room  
as St'mer, cut on Bm. 1098  
Poop 33 ft. Ditto, Forecastle 32 ft. Ditto, Raised Quarter Deck  
Classed 100A1  
Character in Register Book 12.79

Survey, No. 25237 Port London  
OR EXAMINATION AS PER RULE  
Use of Repairs to be clearly stated. Special Survey No. 1 &c.

... on blocks on slipway and the Keel and bottom examined.  
... timber boards and portable ceiling equal to several strakes.  
... each side removed and the cementing of bottom carefully  
... mined and made good where found necessary. The masts,  
... and general equipment attended to.  
... bridge and deep ballast tank has now been fitted  
... approved tracings attached, and the tank tested by  
... ad of water fully equal to the load water line and  
... efficient.  
... pairs through damage; - Iron shell plates on port side  
... before mizen mast renewed and two plates heaved  
... set pair. 2 damaged frames made good; three plates at

Condition of the	Good	Rivets Treenails	Where seen	Good		Good
	do		Breasthooks and Stemson	do	Windlass and Capstan	Good
	do		Transoms, Pointers, and Crutches	do	Pumps	do
Beams & Fastenings	do		Timbers of the Frame at the openings	do	Boats	Four and do
Beams & Fastenings	do		Ditto Ditto at other places	do	Masts, Yards, &c.	do
			Keelsons	do	Condition, how ascertained	On deck &c.
			Clamps and Shelves	do	Sails	Complete and Good
			Ceiling	do	Anchors	No. of 313. 15. 256.
			Rudder	do	Cables	Complete and
			Copper (or Y.M.)	When put on	Hawsers and Warps	Good
			Caulking of		Standing & Running Rigging	
			Bottom, Deck, & Waterways	Good		

... Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
... The requirements of Special Survey No. 1 have  
... been complied with and the vessel put into a good and  
... erient State of repair, "fit for the safe conveyance of  
... and perishable cargoes to and from all parts of the world."  
... is eligible in my opinion to remain as classed and  
... noted S.S. No. 1-83 in the Register Book.

Entry Fee ... £ : : received by me, M.N.  
Special ... £ 3: 3: " 2/6/ 1883.  
"Dam ... £ 3: 3: "  
ate (if required) ... £ : 5: "  
t as per margin...  
e, if any, £ )  
s Minute  
assigned  
100A  
S.S. No. 1-83  
TUESDAY 26 JUNE 1883 18  
James M. Neil  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
© 2020  
Lloyd's Register  
HUL396-0003



front of poop on port side renewed, the Cementing of both  
renewed where found necessary. Ceiling, where removed,  
refitted and the bottom cleaned & painted.



© 2020

Lloyd's Register  
Foundation