

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office.)

Hull No. 5359

No. in Survey held at *London* Date, first Survey *9 Augt* Last Survey *Aug 13 1883*
 g. Book. on the *SS Bell Rock* (No. of Visits) Master *J Sumbuck*

TONNAGE under Tonnage Deck *3258*
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *3539*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. *2287*
 Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.*
 Built at *Hull* When built *1883* *May*
 Owners *J P Garbutt* Port belonging to *Hull*
 Residence
 By whom built *J P Garbutt* Destined Voyage *Honolulu*
 If Surveyed Afloat or in Dry Dock *Afloat Victoria Bk*
 (State Name of Dock)
 Years assigned. Character in Register Book.
 Classed

Last Survey, No. Port
 REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated. Society's Freeboard (if assigned) as painted on Ship
 State dates of any letters respecting this case

At the present time the Bulkheads to the Fore & after Peaks have been tested and made tight. The Water Tight doors in Engine Room Bulkheads have been properly fitted. A Pillar has been fitted to every beam in the Fore Peak. As recommended by the Hull Surveyors in their 1st Entry Report.

Senhouse Martindale

Present Condition of the
 Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter
 Engine Room Skylights
 Coal Bunker, Openings, Lids, &c.
 Scuppers
 Cargo and Main Hatchways
 Hatches
 Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the openings
 Ditto Ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper (or Y.M.) When put on
 (State if on Felt.)
 Cement (if Iron Ship)
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors No. of
 Cables
 Hawsers and Warps
 Standing & Running Rigging

General Observations, Opinion as to Class, &c.

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £ : : 188

Certificate (if required) to be sent as per margin... } £ : :

Travelling Expenses, if any, £)

Committee's Minute
 Character assigned

TUESDAY 14 AUGUST 1883

Surveyor to Lloyd's Register of British and Foreign Shipping.

