

THOS. WILSON, SONS & CO'S  
STEAMERS TO  
HAMBURG. RIGA.  
ANTWERP. CROSTADT.  
DUNKIRK. ST. PETERSBURG.  
COTHENBURG. CONSTANTINOPLE.  
STOCKHOLM. ODESSA.  
CHRISTIANIA. TAGANROG.  
STAVANGER. NAPLES.  
BERGEN. MESSINA.  
DROTHHEIM. PALERMO.  
COPENHAGEN. TRIESTE.  
VENICE.  
STETTIN. BARI.  
DANZIC. ALEXANDRIA.  
LIBAU.  
BOSTON.  
NEW YORK.

Hull, August 14<sup>th</sup> 83



J. Mc. Neil Esq:  
Lloyds Surveyor, Hull

St. Sir,

Your letter of the 13<sup>th</sup> Inst. respecting reclassification of Ys. Bassano duly to hand, & we observe your rules require her ceiling to be lifted to pass the periodical survey -

You are aware of the extensive repairs done to this vessel, in December 1879, when we put in new ceiling, & re-cemented all the holds, under your inspection; extended the Bridge; covered in the Engine room, & many other repairs, of which we annex a list; we think that if the lumber-boards are lifted (there being three strakes on each side) & the cement found in good repair, that this should be sufficient for your purpose -

We

We are scraping & painting the ship inside & out -

We are, St. Sir,  
Yours respectfully  
J. P. Thos Wilson Sons & Co  
Newbold

37

1883  
Hull August 14  
Wilson Sons & Co.

Rec'd 15

re Special Survey No. 3  
on the "Bassano"



© 2020

Lloyd's Register  
Foundation

HUL396-0140 (112)



"Bassano" Dec<sup>r</sup> 1849

New ceiling in all holds & cemented

New chain Locker

Water Tanks moved aft

New solid hatches

New Iron Bhead fore & aft hold

" " " front of Bridge

Cover in from Bridge to aft end of engine

Take away cabin-deck - skylight &c

Fit new maniches

Repair all sluice valves, pumps

Fit two new 10" pumps

Alter & repair steering gear, new leads &c

New Mizzen mast

3 New Derricks

Repair main rigging new main stay

Repair water tanks

Move pumps aft hold

Lighten Boat Davit

2 Iron W.C. companion forward

Repair Windlass new cast-iron hatch chain  
locker

5 New coal hatches under bridge - (P.T.O.)

New castings for Davits Steam steering gear

6 steering gear sheaves 4 bevelled jaw leads -

Boat crutches New derrick hoops Mizzen mast

New Beds for maniches

LN 396-0140 (2/2)



© 2020

Lloyd's Register  
Foundation

Dec 15/8/83