

12/3/84

B.M.

In article to

report - W.L.

Frederick Wiggins by
Charles Wilson, Esq., M.P.

It is submitted that
Mr Wilson be informed that
the freboard which the Committee
consider suitable for a

vessel is not indicated by them
until such vessel has been con-
sidered, and all the particulars re-

ported on by the surveyor. It is
further required that before taking a
case into consideration, the owner should
state what in his opinion is a suitable
freboard for the vessel

12/3/84

The majority of the vessels referred to are
not covered by the Register book of this port
and it is therefore necessary to ascertain the
particulars of each vessel as far as possible

Thanks for your report
I am under the
impression that the
damage was not too deep
and not extraordinary
and rather - might not
your surveyor have
noticed the defects which

to 10/11/84
13/1/84

30. GROSVENOR SQUARE.
W.

Atk 13th
Ans: 19th

MAR. 84
LONDON

W.L.

HUL396-6207

W

Your report declares -
 still you kindly
 inform me the
 Rosario preboard
 on sailing other
 preboard you would
 have given whether
 your preboard is for
 an Atlantic voyage

not for the general
 Baltic trade -

I should like to have
 your preboard for
 all our Baltic
 Mediterranean Atlantic
 steamers
 Yours truly
 Charles A. Wilson