

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPS  
*Wm. Earle Shipbuilding & Eng. Co. Ltd.* *June 29*

*S. Hull.*

<i>June 6.</i>	<i>2</i>	<i>Wale Sec: Steel Plate</i>	<i>6.2 x 1.2 x 2.0 x 1/4</i>	<i>287.8</i>	<i>Cost 1100.</i>
	<i>1</i>		<i>Sketch 2. x 1.8</i>		<i>642.0.</i>
	<i>1</i>		<i>8.6 x 4.0 x 1/4</i>	<i>1.6</i>	<i>654.13.</i>
	<i>4 Bars</i>	<i>Wale Sec: Steel</i>	<i>2 1/4 Rod 9.0</i>		<i>644.0.</i>
	<i>12</i>		<i>1 1/2 x 16.0</i>		<i>634.</i>
	<i>1</i>		<i>1 1/2 x 16.0</i>		
<i>June 5</i>	<i>13</i>		<i>2 x 4.0</i>	<i>340</i>	<i>634.</i>

*A. Stoddart*

HVL 398-00283

When a second test is applied, the result should be recorded in

<i>Fee</i>	<i>..... £</i>	<i>:</i>	<i>:</i>
<i>Expenses</i>	<i>£</i>	<i>:</i>	<i>:</i>
	<i>£</i>	<i>:</i>	<i>:</i>

To be paid by *Manufacturers.*

*A. Stoddart*  
 Surveyor, Lloyd's Register,  
*W. Hartlepool.*

[T. & Son—6000—5/5/85.]

HVL 398-0029

© 2019 Lloyd's Register Foundation