

Special Bailey Theitham 14<sup>th</sup> April 86  
 Chind to Drypool In NER

M 924 9/23/85

1S	3	Boiler Plates	15.0	5.4 1/4	7/8	3	7	2	.
2	1	9295	16.10	5.4 1/2	7/16	1	6	.	21
1D	1	996	5.4 1/2	1.0 1/2	7/16	1	1	.	21
2	1	7944.	4.11 1/4	2.9	1/2	2	.	.	21
1CT	1	1964	3.8	.	.	5	.	.	21
2	2	3293. 8790.	5.0	2.11	.	4	2	.	21
1CS	2	1869. 1864.	6.10	2.10 1/2	.	5	3	.	21
2	2	3038. 8790	5.4	2.10 1/2	.	6	.	.	21
3	2	2052.	5.10	2.11	.	6	.	.	21
4	2	2052. 8794.	5.4	2.11 1/2	.	5	.	.	21
5	1	1480	6.8	4.4 1/2	.	16	.	.	21
1CB	1	2513	9.10	5.5	3/4	3	1	.	21
2.	2	8004. 8060.	8.1	2.6	1/2	2	3	.	21
FR	2	8653	3.9	2.0	1/2	1	3	.	21
CP	2	8440. 14114	6.10	1.5	7/16	5	2	.	21
CD	1	1897	6.0	5.4	3/4	1	4	.	21
1TP	1	1581.	5.11	5.6 1/2	3/4	19	1	.	21
2	2	1400.	15.4	5.4	3/4	15	.	.	21
TP	1	9020.	15.5 1/4	.	7/4	12	18	.	21
MB	1	2945.	14.9. 4. 7/16 and	.	.	.	.	.	21
FP	1	7966.	.	.	.	.	.	.	21
	<u>32</u>								

J. H. S. 17. 4. 81 -  
 Surveyor 1. of Lloyd's Register

FF 1

L.B. Wilsons 20200. 19883. 1583  
 6044. 10475.

Batch 4 1/2 8 7 11



© 2019

Lloyd's Register  
 Foundation

HVL 398-0142