

(Received in London Office.

Tests of 3 Steel Plate-manufactured by Messrs D. Colville & Sons of Motherwell
for Boiler No. 286 to be constructed by Messrs The Earle & Co. of Hull
for their S. S. N^o 286

Date first visit April 24th 1951 last visit No. of Visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ / _____ samples as set forth below, and the temper and bending tests as required by Circular N^o 438.

hm
4/5/85

Expenses £ : :

£ : .

To be paid by

A. M. Dove.

Surveyor, Lloyd's Register,

Glasgow.