


No. 2659

(Received in London Office,



TESTS OF BOILER STEEL.

Tests of / Steel plate manufactured by *Steel Co. Scotland* of *Glasgow*
for Boiler No. *78*. to be constructed by *Baird Latham* of *Null*
for

Date first visit last visit No. of visits

The *1* plate specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to *1* samples as set forth below, and the temper and bending tests *as required by Circular No 438*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	<i>62 1/2 x 7-7/8. 3/4</i>	<i>352</i>		<i>8847</i>	<i>75</i>	<i>115</i>	<i>862</i>	<i>243</i>	<i>28.1</i>	<i>21.</i>	

Fee £ : :
Expenses £ : :
£ : :

To be paid by *The Steel Co.*

John Sanders
Surveyor, Lloyd's Register,

Glasgow
Lloyd's Register Foundation

D.G.
11/6/85