

No. _____

(Received in London Office, _____)

TESTS OF BOILER STEEL.

Tests of 147 Steel bars manufactured by J. Brown & Co. L^{td} of Sheffield
 for Boiler No. _____ to be constructed by Earles Co. of Hull
 for _____

Date first visit 21/4 last visit 22/4/86 No. of visits 2

The bars specified in the accompanying copy of Advice Notes were rolled from
 1 charges. The tensile test has been applied to 5 samples as set forth below,
 and the temper and bending tests to each bar

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
		567		84	dia.	area					
				.72		.407	11	27	24		
				100	.71	.359	11	27.8	24		
				156	.85	.567	12.25	26.8	27		
				138	"	"	15	26.4	26		
				434	.99	769	21.5	27.9	25		

Fee £ : :

Expenses £ : :

£ : :

To be paid by _____

 © 2019 David Twiss
 Surveyor, Lloyd's Register
 Lloyd's Register Foundation

HVL 398-0279