

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office, .....

No. ....

**TESTS OF BOILER STEEL.**

Tests of 40 Steel bars manufactured by J. Brown & Co. Ltd of Sheffield  
 for Boiler No. .... to be constructed by Bailey & Suthorn of Hull  
 for .....

Date first visit 26 last visit 27/5/86 No. of visits 2

The bars specified in the accompanying copy of Advice Notes were rolled from  
1 charges. The tensile test has been applied to 3 samples as set forth below,  
 and the temper and bending tests to each bar

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	<u>Boilers</u>	<u>965</u>		<u>331</u>	<u>1.13</u>	<u>1.002</u>	<u>27.5</u>	<u>27.4</u>	<u>28</u>		
		<u>"</u>		<u>337</u>	<u>"</u>	<u>"</u>	<u>"</u>	<u>"</u>	<u>26</u>		
		<u>"</u>		<u>353</u>	<u>"</u>	<u>"</u>	<u>28</u>	<u>27.9</u>	<u>26</u>		

Fee ..... £ : :  
 Expenses £ : :  
 £ : :                     

To be paid by .....

 David James  
 Surveyor, Lloyd's Register,  
 Lloyd's Register  
 Foundation  
 HVL 398 - 0297

*S. S. Adventure*

*Hul No: 5987*

HUL 398-0297



© 2019

Lloyd's Register  
Foundation