

Case of the s.s. "Albanian," No: 279 in the
Reg. Bk. built in 1855, classed 90A1 11/84
SS No. 3-85.

This vessel is reported by the Society's
Surveyor at Hull as having undergone, in
the course of repairs of damage through
grounding, the requirements of the
special survey No: 3, except that the
ceiling in the fore and after holds has
only been lifted to the extent of four
strakes on each side, instead of
entirely. But as the ceiling was all
renewed at the last special survey (1885)
the Surveyor submits the vessel as
worthy the Committee's favourable
consideration with a view to the
assignment of the record of SS No. 3-7/88,
as requested by the Owners.

The Classing Committee decided on
the 17th July to refer the case to the
General Committee.

A.S. 18/7/88

As Mr. Murrell's report for G @
18/7/88 B.M.

It is submitted that as only 4 strakes
of ceiling on each side ~~only~~ in the fore & after
holds have been removed, instead of the whole
of the ceiling as required by the rules, therefore
the vessel eligible to have S.S. No 3 recorded, as suggested
by the Surveyor, and the vessel is 33 years old
the rules should be fully complied with
before SS No 3 be recorded in the Reg. Bk.

19/7/88

B.M.

J.H.

W.D.