

No. 2208

(Received at London Office)
 LLOYD'S REGISTER OF SHIPPING
 28 AUG. 88

TESTS OF BOILER STEEL.

Tests of Steel Plate manufactured by Heartale Iron Works Co of Spennymoor
 for Boiler No. 91 to be constructed by Bailey, Seaham of Hull
 for

Date first visit 22.8.88 last visit _____ No. of visits 1

The Plates specified in the accompanying copy of Advice Notes were rolled from
1 charges. The tensile test has been applied to 1 samples as set forth below,
 and the temper and bending tests were good

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	T. ns.	Tons.		
	<u>Furnace</u>		<u>6101 B</u>		<u>8</u>	<u>150</u>	<u>0.75</u>	<u>21.65</u>	<u>28.8</u>	<u>28.</u>	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

© 2020

Wm R. Austin
 Surveyor, Lloyd's Register.
Herbert Kenwood
 Foundation