

Sent to Chief Surveyor 15. 8. 92

Received from Chief Surveyor

VESSEL'S NAME

Gomes IV

Report Jul No. 8344

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

When due

It is submitted the Surveyors should be requested to take the first opportunity to furnish the length of the bridge house for record in the Register Book.

The particulars of the Donkey Boiler
have been received & found correct
for 60 lbs working pressure

M.A.

15. 8. 92

Noted. Full 16/8/92

J.P.B.

S.M.

© 15. 8. 92

Lloyd's Register
Foundation

HUL406-0400