

reference

M.

Lloyd's Register of British and Foreign Shipping.

Bank Chambers, Hull.

Sept. 13th 1895.

LLOYD'S REGISTER
LONDON.

RECP. 1 SEP. 1895
ANSR

Sir,

In reply to your letter of
yesterday's date, having reference to
the machinery report of the trawler
"Newfoundland", I beg to say that no
doubling plate is fitted on the front
tube plate, in the wide water space.

With regard to the mean pitch of
the stays in the tube plates, I have to
say that 14 1/4" marked on the report is
in error. It should read 11 7/8 ins.

I am,
Sir,

Your obedient servant
H. P. Cornish

The Secretary,
London.



Lloyd's Register
Foundation

110611-0083

the same plan

ENG
Diam
Diam
Diam
No. of
No. of
No. of

1895

REGISTERED
LONDON

RECEIVED
1895

[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page.]

[Handwritten signature or initials.]

14 SEP. 1895

Hotel
14.9.95



Lloyd's Register
Foundation