

The Surveyor should be requested to state whether the mean pitch of the stays, in the tubes plates of the main boiler, is $14 \frac{1}{4}$ " as stated on his Report, as only 12" would be approved of by the Rules, & whether there is a doubling plate on the front tube plate in the wide water space.

It would prevent needless delay if the boiler drawings were forwarded with the first Entry Reports.

Wm to Hull
12/9/95.



© 2019
L.R.S.

12.9.95
Lloyd's Register
Foundation

HUL411-0084