

Surveyor 6.11.95 Received from Chief Surveyor _____
NAME Steel S.S. "Magnetic" Report Hull No. 10,069

marks of the Chief Surveyor are desired on this Case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points represented in the endorsement. —Extract from Sub-Committee's Report 24/5/92.

Surveyor Classification

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is worthy to be classed 100 A 1 (Steel) Stm. Trawler as recommended.

100 A 1 (Steel) Stm. Trawler

1 DK.

B.K. 7 1/2" Cern

G.B.

H.M.

6.11.95



© 2019

Lloyd's Register Foundation

HULL 11-0234

of Angles or Tee Bars to Web Frames	✓		✓		LONGITUDINAL,,	✓		
PLATES to Stringers between)	✓		✓			✓		

7
7
7
7
u
Inches Ship.
19
v
v
v
+
v
v
v
v
v
3
v
v
v
3
v
v
v
v
v
v
2
3
8
5