

E. / Lloyds Register of British
and Foreign Shipping.

enc LLOYDS REGISTER
LONDON. Bank Chambers, Hull.

RECR 24 AUG. 96.

ANSB

August 22nd 1896.

The Secretary,
London

Sir.

In reply to your letter of the 19th inst., having reference to the Machinery Report No. 5603 of the "Monarch," we are respectfully requested by Mr. Jones to state that the size of cylinders should have been in the first report 16" & 34" and not 16" & 33" as stated, which was a clerical error.

These engines were built for stock purposes and have been lying in Mess^{rs} Bailey's Works until the present time, when they were sold to Mess^{rs} Simpsons, upon condition that the A.P. Cylinder was reduced to 5" by means of a liner and the tunnel shaft increased to 5 $\frac{7}{8}$ " dia.

The Boiler & engines have now been fitted to this steamer for the first time. The main



© 2019
Lloyd's Register
Foundation

HUL413-0022

ge pumps one Diameter of ditto $2\frac{3}{8}$ Stroke 13' Can one be overhauled while at
e ed in
e ro
ove
z sp
m
tu

Boiler has been standing in the Boiler
works under cover and perfectly dry. We
therefore did not consider it
necessary to examine the boiler internally.
The report sent is returned herewith.

We are,

Sir,

Your obedient servant,
for The Surveyor,
W. Rowell



© 2019

Lloyd's Register
Foundation

24 AUG. 1890

Also for Mr. Hill to note.

LL
24.8.96



© 2019
Lloyd's Register
Foundation