

test have also been supplied

S.S. "LUIS VIVES" ex "ARIOSTO".

It is submitted the Hull Surveyors should be informed that while the Committee have assigned the figure 1 on their report No. 22678, which states that the marks on the anchors and chains have been verified, it is considered that their action in this case has not been satisfactory and greater efforts should have been made to ascertain the marks and obtain the certificates before forwarding their reports No. 22661, wherein it was stated that the marks on the cables were worn out, and could not be identified, and that only the weight of the second bower anchor could be obtained.

Rev. to Hull 5/7/10.

C.B.

5.7.10.

HOL 426-0116

Condition, how a
(State if rec
Sails.....
Equipment let
Anchors, No. o
Cables (state
" length...
" Rule len
(per
Hawser & W
Standing & R

l in the Re
main as ch

f Brit



© 2020

Lloyd's Register
Foundation

HOL 426-0115