

I have only seen this Ship once, viz Nov^r 3/60 when in conjunction with Mr Taylor found her Caulked from Middle of Bilges upwards, and in hand Caulking remainder of Bottom. Painted from lower part of Wale upwards.

Found a long after Flood of Bottom planking in third Strake up from Keel on the Port side of Gunwale, badly decayed, recommended that it be replaced, and ~~the~~ Plank on the Starb^d side of inferior American Elm, requiring to be cut into, and further examined: also a length of Plank here of African Oak on the Port side abreast of Fore Rigg very defective, recommended that this be replaced, and the whole of the Planks here to have the paint scraped off, and further examined: there was also a deficiency of Gunwale in some places.

The Builder, and the resident Surveyor promised that the whole of the above deficiencies should be made good as then recommended, which by the Report appear to have been done

March 10/61 J. S. Martin



© 2021

Lloyd's Register
Foundation