

Reference

S

Lloyd's Register of British and Foreign Shipping.

35 Lower Cruesell St

Spawick June 1st 1892

LLOYD'S REGISTER.

LONDON.

REC'D 2-JUN. 9

ANS'D

A.C. Dryhurst Esq

Dear Sir

Re "Maori"

In answer to Yours in reference to the above the foremast have been take out, the head out of Turner Cottons ~~put~~ up a length scarp on under the deck, a new fore Yawl is being fitted, the Ringlehead is being scarpheel, the 12 planks on the bows have been repaired by a quantity of pieces let into same. Some of the chain plate have been repaired, the Rascal Quarter Deck have been caulked. Some of the bolts in Riddle's knees removed, there have been nothing done to the ceiling the Hold was not cleared, the chains have not been ranged. The have taken in the whole of the cargo the repair are under the Survey of Mr Turner the Survey to the Board of Trade -

(From the appears of the vessel after she took the ground, after coming out of dry dock, I believe the port bulge is broken)

Yours Obedt
E. Roberts

18929-0124

Referred to the Chief Surveyor.

afw

2/6/92

Also for Mr. Hill to note.



© 2021

Lloyd's Register
Foundation