

Lloyd's Register of British & Foreign Shipping.



35 Lower Llewellyn

LLLOYD'S REGISTER,

LONDON.

Ipwich 20th 1892

ANBR

A. G. Dryden Esq

Dear Sir R. "Maori"

In answer to your telegram in
reference to the above, at present I have
heard nothing from the owner or my friends
of son in reference to the repairs of this vessel
The Holidays may be the cause of the
delay

Yours Obedient

Edw. Roberts



© 2019

Lloyd's Register
Foundation

For Chief Surveyor

A.S.

21/4/92

G.B.

It is submitted that
Mr Robertson should be instructed
to report, in due course, the repairs
that may be carried out before
the vessel sails.

Dr. to Sps. 21/4/92

G.B.
J.H.B. 21.4.92.



© 2019

Lloyd's Register
Foundation