

Reference

LOYD'S REGISTER
LONDON.
RECEIVED 1- APR. 92
ANSR

Lloyd's Register of British and Foreign Shipping.

35 Lower Circular St. Spawood

March 31st 1892

A. G. Dryhurst Esq.

Dear Sir

Re "Maori"

In answer to your of the 30th inst in reference to the
above. The slack bolts in rigger knees have not been renewed.

The fore mast head has a round spar about 20 feet
long lashed to the after side of same. Secured by a chain thrapton
round mast and set up with wedges. as span by the Bay of
Aurifer at Queenstown. to enable her to sail from that port
to Wivenhoe. I am informed by Mr Forrest & sons. that they
propose to fitt two or three iron screw hoops over & round
same for the voyage out.

In my opinion she is not safe for the
Contemplated voyage. The fore Larer is also defective

Yours Obd Servant
Chas Roberts



Lloyd's Register
Foundation

IPS429-0131

Referred to the Chief Surveyor.

agw

1/4/92

Also for Mr. Hill to note.



© 2019

Lloyd's Register
Foundation