

Sent to Chief Surveyors 28. 3. 92

Received from Chief Surveyors

VESSEL'S NAME

"Maori"

Report

Ln

No.

2325For the remarks of the CHIEF SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~~~S.S. No.~~~~date~~~~B.S. date~~

It is submitted Mr Robertson should ascertain & state for the information of the Committee whether the one or two rider knee bolts found slack by the Queenstown surveyor have been renewed, and whether the foremast head found defective has been made good. The surveyor should send his reply promptly.

G.B.

28. 3. 92.

Ltr to Ltr
30/3/92.

© 2019

Lloyd's Register
Foundation

IPS429-0135