

REPORT of SURVEY for REPAIRS.

Change of Owners

No. *87* Survey held at *London* Date *June 9th* 184*5*
 on the *Brk Vm Ship John Laird* Master *G. H. Bryant*
 Tonnage *264* Built at *Liverpool* When built *1842*
 By whom built _____ Owners *J. Nutting*
 Port belonging to *London* Destined Voyage *Hong Kong*
 If Surveyed Afloat or in Dry Dock *London Dock*

Dec. 29 1845

Last Survey, No. _____ Classed _____

Port *A*

REPAIRS *See last report*

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, *Appears in an efficient to retain her present class*
A 1 for one year

A. M. W. L. M.

The Amount of Fee.....£ / : : is received by me, *H.*

Certificate (if required) _____

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

LRON430-0100