

REPORT of SURVEY for REPAIRS.

Iron Ship (448) 12019
 No. *12019* Survey held at *Liverpool* Date *May 25* 18*53*
 on the *Barque Marguerite* Master *C. Barker*
 Tonnage *397* Built at *Shields* When built *1848*
 By whom built _____ Owners *Clay & Co*
 Port belonging to *Shields* Destined Voyage *to port of*
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. _____ Port _____ Classed *A I*

REPAIRS *Has now been scraped clean & coated and also had the Rudder secured. The iron plating in the flat of the bottom inside is wearing away about 8 of an inch.*

Present Condition of the

Decks <i>good</i>	Trunnails	Windlass and Capstan <i>good</i>
Waterways <i>good</i>	Breasthooks and Stemson	Pumps <i>good</i>
Comings <i>good</i>	Transoms, Pointers, and Crutches	Boats <i>2 2</i> <i>good</i>
Upper Deck Beams & Fastenings <i>good</i>	Timbers of the Frame	Masts, Yards, &c. <i>good</i>
Lower Deck Beams & Fastenings <i>good</i>	Keelsons	Sails <i>well found</i>
Planksheers <i>good</i>	Clamps and Shelves	Anchors No. of <i>23 Buns 1 1/2 1 1/2</i>
Sheerstrakes <i>iron</i>	Ceiling	Cables
Topsides <i>iron</i>	Rudder <i>good</i>	Hawsers and Warps <i>all good</i>
Wales <i>iron</i>	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter <i>iron</i>		

General Observations and Opinion,

Is now in a fit and efficient state for the safe conveyance of dry and perishable cargoes, to and from all parts of the world, and in my opinion I should retain her present character

The Amount of Fee.....£ - : - : is received by me,

Special..... / : / : -

Certificate (if required) ..: 10 : -

Committee's Minute *31st May 1853*

Character assigned *A* *1* *SD*



© 2019

Lloyd's Register Foundation

IRON431-0008

REPORT OF SURVEY FOR REPAIRS

Margaret 12019

