

Change of Owners
1957

REPORT of SURVEY for REPAIRS.

Rec. 11/8/59

No. 15914 Survey held at Liverpool Date Augt 2 to 8 1859
on the ²⁹³2m screw Steamer Boetia Master W. Simpson
Tonnage 951 Built at Shields When built 1855
846
By whom built _____ Owners Bibby & Co
Port belonging to Liverpool Destined Voyage Genoa
If Surveyed Afloat or in Dry Dock in Dry Dock & Afloat

Last Survey, No. 1489 Port Liverpool Classed 9 A 1
58

REPAIRS

Has had the ceiling taken off for the examination of the inner surface of the plating, and the rivets; which were found to be in good condition. And the bottom has been coated.

Present Condition of the

Decks	<u>Good</u>	Trunnels		Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	<u>Good</u>	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	<u>well found</u>
Planksheers	"	Clamps and Shelves	"	Anchors	No. of <u>3</u> <u>Bowens, Shunt & Hedges</u>
Sheerstrakes	"	Ceiling	"	Cables	<u>well found</u>
Topsides	"	Rudder	"	Hawsers and Warps	<u>well found</u>
Wales	"	Copper	When put on	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. appears satisfactory

Is in an efficient state, fit for the conveyance of dry and perishable cargoes with safety, to and from all parts of the world, and in my opinion should be continued as classed.

The Amount of Fee.....£ 1 : " : " is received by me,

Special..... 2 : 2 : " 9/8/59

Certificate (if required) " : 5 : "

Committee's Minute 12 August 1859

Character assigned 9 A 1



© 2019

Lloyd's Register
Foundation

IRON434-0047

"Baetia" 15914



© 2019

Lloyd's Register
Foundation