

ANNUAL SURVEYS.

Re 27/10/59

No. 1003 Survey held at Liverpool Date Oct 4/59 1859
 on the (Iron) Ship Hurrican Master J. J. S. Look
 Tonnage 980 Built at Glasgow When built 1853
 By whom built C. J. J. J. Owners Martin & Co.
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock in 92 Dⁿ & Afloat

Last Survey, No. 1495 Port of Iron Classed 9-A
58

present Condition of the

Decks	Transoms	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Galley	Bottom & Keel	Standing & Running Rigging
Plating	Copper & Coated	
Plank (Bottom) and Counter		

Good as far as seen

When put on appresent

Apply Good

Well formed

No. of 3 Bow / 1 Stern 2 Kedges

Good

Good

Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways all satisfactory

The wood stanchions & waterways betwixt the poop & Forecastle have now been caulked. It is reported that the greater part of the ceiling was lifted or renewed in London on the last date of survey from examination made at the different openings inside & the condition of the whole of the outside plating. She appears in a condition for the safe conveyance of dry &

Committee's Minute

25th November 1859

Character assigned

9-A

Certificate (if required)

See L 2-2-0 23. 11. 59 Al.

MANUAL OF THE

16039
Hurricane

Blencathra



© 2019

Lloyd's Register
Foundation