

# REPORT of SURVEY for REPAIRS.

No. 10 Survey held at London Date March 2<sup>d</sup> 1860  
 on the Ship Abdul medjid Master Willie  
 Tonnage 400 Built at Glasgow When built 1854  
 By whom built — Owners J. W. Fell.  
 Port belonging to Glasgow Destined Voyage —  
 If Surveyed Afloat or in Dry Dock King & Queen dry dock.

Last Survey, No. 1794 Port Spain Classed 12. A. 1. in 1854.  
 58

## REPAIRS

On the 2<sup>nd</sup> inst lifted a length of Ceiling in wake of Garb<sup>l</sup>. Strake the Rivets in the edge proved bad. The Master not having authority to renew them. the following is an extract from Notice Card left for the Owners. —

"The whole of the Rivets which have been thoroughly eaten away at the heads may be renewed and the Ceiling as pointed out, lifted for further survey."

N.B. It is reported she has left for the Clyde.

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

## General Observations and Opinion,

## Caulking of Bottom, Deck, & Waterways.

The Ship having been undocked without the necessary repairs We are of opinion she is in an unsafe state or condition and ineligible to retain her present Character

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 16<sup>th</sup> March 1860

Character assigned Expense Character

Samuel Roberts

J. W. Fell



© 2019

Lloyd's Register Foundation

IRON434-0188