

ANNUAL SURVEYS.

No. 16819 Survey held at Liverpool Date 16th Feb 1861
 on the Iron S.S. Ship "Albanian" Master Power
 Tonnage 1034 Built at Port Glasgow When built 1855
 By whom built Owners Bibby & Co
 Port belonging to Liverpool Destined Voyage Medit^m
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 2294 Port of Iron Classed 9 A 1
60 10

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3 bows 1 Stn 2 Wedges</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Paint</u> When put on <u>present time</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways appeared good

Is in a fit state for the safe conveyance of dry and perishable Cargoes to and from all parts of the World & eligible to retain her present Character
In consequence of damage 14 plates have been taken off about light water mark on starboard side, the plates straightened and replaced, the damage extended no further

Committee's Minute 5th March 1861.

Character assigned 9 A 1 W

Wimshurst

LK.

Certificate (if required)

No. 937 Survey held at Liverpool Date Feb 16 to 22 1861
 on the Iron Bth "Atahualpa" Master Wheeler
 Tonnage 497 Built at Liverpool When built 1857
 By whom built Owners W & J Lyster
 Port belonging to Liverpool Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock in 92nd

Last Survey, No. 2083 Port of Iron Classed 12 A 1
00

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3 bows 1 Stn 1 Wedge</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Bottom chains</u> When put on <u>at present</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways All appear satisfactory

Appears in a condition for the safe conveyance of dry & perishable cargoes to & from all parts of the world & recommends her to continue as Classed

Committee's Minute 5th March 1861.

Character assigned 12 A 1 W

Certificate (if required)

IRON434-0454

"Marian"

"Atahualpha" 16819



© 2019

Lloyd's Register
Foundation